

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of) MAIL STOP / AF
Gerard Baumgartner et al.	Group Art Unit: 3726
Application No.: 10/706,054) Examiner: JOHN C HONG
Filed: November 13, 2003) Confirmation No.: 6354
For: MACHINE FOR PRESENTING A TIRE WITH THE AXIS HORIZONTAL))))

REQUEST FOR RECONSIDERATION

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

In response to the Office Action dated November 15, 2005, reconsideration of the subject patent application is requested.

Applicants wish to thank the examiner for the interview accorded the undersigned.

During the interview, the merits of the invention were discussed, in particular the fact that the support structure is arranged to contact <u>solely</u> a toric section of the tire located between the upright and a vertical plane containing the rotation axis.

Stated another way, the portion of the tire disposed to a side of the vertical plane opposite the upright is not supported.

That feature is demonstrated in the attached marked-up copy of Fig. 2 of the application, where it can be seen that the tire is supported solely to the left of the vertical plane containing the axis of rotation, i.e., it is supported solely between the upright 2 and the vertical plane.

Attorney's Docket No. 1033818-000021

Application No. 10/706,054

Page 2

The claimed support mechanism is not only simplified, it provides

unobstructed access to a major portion of the tire.

In contrast, the support structure shown in Fig. 3 of Painter comprises support

rollers located to both sides of the vertical plane which contains the tire's axis of

rotation, as shown in the attached marked-up copy of Fig. 3 of Painter. It can be

seen that with Painter's apparatus, access to the tire is more obstructed than with the

claimed apparatus.

Accordingly, it is submitted that claim 15 distinguishes patentably over

Painter.

If the rejection of claim 15 is to be maintained, it is respectfully requested that

an explanation be provided as to how the expression "the support structure arranged

to contact solely a toric section of the tire located between the upright and a vertical

plane containing the rotation axis" is considered to be readable on Fig. 3 of Painter.

Respectfully submitted,

BUCHANAN INGERSOLL PC

Date: February 15, 2006

Registration No. 25,813

P.O. Box 1404

Alexandria, Virginia 22313-1404

(703) 836-6620